



**THROUGH-HOLE SOLDERING  
MECHANICAL ASSEMBLY, HARDWARE**



**MECHANICAL ASSEMBLY – HARDWARE**


Mechanical assembly hardware refers to the mounting of electrical and electronic components to a printed wiring board (PWB), or any other types of assemblies requiring the use of screws, bolts, nuts, fasteners, clips, component studs, adhesives, tie downs, rivets, connector pins, etc.

See Section 6.01 "Through-Hole Soldering, General Requirements", for common accept / reject criteria.




**PREFERRED  
BLIND FASTENER SEQUENCE**

Fasteners shall be assembled and installed in the sequence depicted, or per engineering documentation.  
**Note: Self-tapping fasteners shall not be used for flight hardware.**  
[Best Workmanship Practice](#)




**PREFERRED  
FASTENER SEQUENCE**

Fasteners shall be assembled and installed in the sequence depicted, or per engineering documentation.  
[Best Workmanship Practice](#)



**PREFERRED  
THREAD PROTRUSION (L)**

A minimum of 1-1/2 threads shall extend beyond the threaded hardware (e.g., nut), unless otherwise specified by the engineering documentation.  
[Best Workmanship Practice](#)




**ACCEPTABLE  
THREAD PROTRUSION (L) - MINIMUM**

Thread extension may be flush with the edge of the threaded hardware when complete thread engagement can be visually verified, or where protruding threads could present an interference (electrical / mechanical) or snag threat.  
[Best Workmanship Practice](#)

**NASA WORKMANSHIP STANDARDS**


	<b>NATIONAL AERONAUTICS AND SPACE ADMINISTRATION</b>  JOHNSON SPACE CENTER HOUSTON, TEXAS USA 77058	Released: 06.27.2002	Revision:	Revision Date:
		Book: 6	Section: 6.03	Page: 1

**THROUGH-HOLE SOLDERING  
MECHANICAL ASSEMBLY, HARDWARE (cont.)**



**UNACCEPTABLE  
IMPROPER FASTENER SEQUENCE**

The hardware is missing or improperly installed.  
[Best Workmanship Practice](#)



**UNACCEPTABLE  
LOOSE FASTENER**

The fastener is not completely tightened, resulting in the incomplete compression of the lock washer.  
[Best Workmanship Practice](#)




**ACCEPTABLE  
MOUNTING HOLE SURFACE**

The surfaces of mounting holes shall be smooth and level, ensuring the mounting hardware will exert even pressure when installed.  
[Best Workmanship Practice](#)



**UNACCEPTABLE  
UNEVEN MOUNTING SURFACE**

Excess solder on the mounting hole surface prevents the mounting hardware from properly seating.  
[Best Workmanship Practice](#)



**UNACCEPTABLE  
HOLE OBSTRUCTION**

Parts and components shall be mounted so that they do not prevent the proper fill of plated-through holes required to be soldered.  
[Best Workmanship Practice](#)



**UNACCEPTABLE  
MISSING TERMINATION LUG**

Wires shall not be wrapped around a screw terminal.  
[Best Workmanship Practice](#)

**NASA WORKMANSHIP STANDARDS**

	<b>NATIONAL AERONAUTICS AND SPACE ADMINISTRATION</b>  JOHNSON SPACE CENTER HOUSTON, TEXAS USA 77058	Released: 06.27.2002	Revision:	Revision Date:
		Book: 6	Section: 6.03	Page: 3

THROUGH-HOLE SOLDERING  
MECHANICAL ASSEMBLY, HARDWARE (cont.)

THIS PAGE IS  
INTENTIONALLY BLANK.


THROUGH-HOLE SOLDERING  
MECHANICAL ASSEMBLY, HARDWARE (cont.)



**ACCEPTABLE  
THREAD PROTRUSION (L) - MAXIMUM**

Thread extension should not be more than 3.0 mm (0.12 in.), plus 1-1/2 threads for bolts or screws up to 25 mm (0.984 in.) in length, or 6.3 mm (0.248 in.) plus 1-1/2 thread for bolts / screws over 25 mm (0.984 in.) in length.


[Best Workmanship Practice](#)



**UNACCEPTABLE  
EXCESS THREAD PROTRUSION (L)**

Excess thread protrusion represents an assembly, interference, and electrical separation problem, as well as adds unnecessary weight to the assembly.


[Best Workmanship Practice](#)



**ACCEPTABLE  
ELECTRICAL CLEARANCE (C)**

The mounting of hardware shall not violate minimum electrical spacing requirements.


[Best Workmanship Practice](#)



**UNACCEPTABLE  
IMPROPER ELECTRICAL CLEARANCE (C)**

The mounting hardware violates minimum electrical spacing requirements. This may result in electrical shorts or mechanical stress to the nearby circuit trace.


[Best Workmanship Practice](#)



**ACCEPTABLE  
FASTENER ASSEMBLY**

The fasteners are properly installed and tight. Split-ring lock washer is fully compressed.

[Best Workmanship Practice](#)



**UNACCEPTABLE  
IMPROPER FASTENER SEQUENCE**

The lock washer has been installed against a nonmetallic / laminate surface. The flat washer is missing.

[Best Workmanship Practice](#)

**NASA WORKMANSHIP STANDARDS**



NATIONAL AERONAUTICS AND  
SPACE ADMINISTRATION  
JOHNSON SPACE CENTER  
HOUSTON, TEXAS USA 77058

Released: 06.27.2002	Revision:	Revision Date:
Book: 6	Section: 6.03	Page: 4

**NASA WORKMANSHIP STANDARDS**



NATIONAL AERONAUTICS AND  
SPACE ADMINISTRATION  
JOHNSON SPACE CENTER  
HOUSTON, TEXAS USA 77058

Released: 06.27.2002	Revision:	Revision Date:
Book: 6	Section: 6.03	Page: 2